



AIRPORT ADVISORY

DATE: April 9, 2003

TO: King County International Airport Tenants
distributed by e-mail and fax

FROM: Jamie Runyan, Airport Operations & Compliance Officer

SUBJECT: Surface Measurement Activity Tonight on Main Runway 13R/31L

As you are aware, our regular monitoring inspection program for main runway 13R/31L had identified a potential area of settlement between Bravo-3 and Bravo-4. Last month, survey and testing activities were performed in this area and, as a result, further examination of an additional 4,000 feet of runway is now required.

Tonight a crew will be using portable equipment to measure elevation changes along the main runway. This surface testing **activity is scheduled to begin at 21:00 hours Wednesday, April 9th and finishing at approximately 09:00 hours on Thursday morning, April 10, 2003.**

The **testing will not require closure of runway 13R/31L** as the measuring activities can be temporarily suspended. A NOTAM will be issue for Personnel and Equipment Working (PAEW) on 13R/31L with ten minutes Prior Permission Required (PPR). The short runway 13L/31R will remain open. **Please check NOTAMS for current information.**

We apologize for any inconvenience caused by this short notice. Your continued patience and cooperation in allowing the Airport to further evaluate the runway surface and design repairs is greatly appreciated. Should you have any questions, please contact me directly at (206) 296-7332.

*** TX REPORT ***

TRANSMISSION OK

TX/RX NO 2953
CONNECTION TEL 95211865
SUBADDRESS
CONNECTION ID AIRLIFT NORTHWES
ST. TIME 04/09 15:47
USAGE T 00'23
PGS. SENT 1
RESULT OK



KCTA AIRPORT ADVISORY

DATE: April 9, 2003

TO: King County International Airport Tenants
distributed by e-mail and fax

FROM: Jamie Runyan, Airport Operations & Compliance Officer

SUBJECT: Surface Measurement Activity Tonight on Main Runway 13R/31L

As you are aware, our regular monitoring inspection program for main runway 13R/31L had identified a potential area of settlement between Bravo-3 and Bravo-4. Last month, survey and testing activities were performed in this area and, as a result, further examination of an additional 4,000 feet of runway is now required.

Tonight a crew will be using portable equipment to measure elevation changes along the main runway. This surface testing activity is scheduled to begin at 21:00 hours Wednesday, April 9th and finishing at approximately 09:00 hours on Thursday morning, April 10, 2003.

The testing will not require closure of runway 13R/31L as the measuring activities can be temporarily suspended. A NOTAM will be issue for Personnel and Equipment Working (PAEW) on 13R/31L with ten minutes Prior Permission Required (PPR). The short runway 13L/31R will remain open. Please check NOTAMS for current information.

We apologize for any inconvenience caused by this short notice. Your continued patience and cooperation in allowing the Airport to further evaluate the runway surface and design repairs is greatly appreciated. Should you have any questions, please contact me directly at (206) 296-7332.

*** TX REPORT ***

TRANSMISSION OK

TX/RX NO 2952
CONNECTION TEL 97631894
SUBADDRESS
CONNECTION ID
ST. TIME 04/09 15:47
USAGE T 00'18
PGS. SENT 1
RESULT OK



KCIA AIRPORT ADVISORY

DATE: April 9, 2003

TO: King County International Airport Tenants
distributed by e-mail and fax

FROM: Jamie Runyan, Airport Operations & Compliance Officer

SUBJECT: Surface Measurement Activity Tonight on Main Runway 13R/31L

As you are aware, our regular monitoring inspection program for main runway 13R/31L had identified a potential area of settlement between Bravo-3 and Bravo-4. Last month, survey and testing activities were performed in this area and, as a result, further examination of an additional 4,000 feet of runway is now required.

Tonight a crew will be using portable equipment to measure elevation changes along the main runway. This surface testing activity is scheduled to begin at 21:00 hours Wednesday, April 9th and finishing at approximately 09:00 hours on Thursday morning, April 10, 2003.

The testing will not require closure of runway 13R/31L as the measuring activities can be temporarily suspended. A NOTAM will be issue for Personnel and Equipment Working (PAEW) on 13R/31L with ten minutes Prior Permission Required (PPR). The short runway 13L/31R will remain open. **Please check NOTAMS for current information.**

We apologize for any inconvenience caused by this short notice. Your continued patience and cooperation in allowing the Airport to further evaluate the runway surface and design repairs is greatly appreciated. Should you have any questions, please contact me directly at (206) 296-7332.

*** TX REPORT ***

TRANSMISSION OK

TX/RX NO 2954
CONNECTION TEL 97680483
SUBADDRESS
CONNECTION ID
ST. TIME 04/09 15:49
USAGE T 02'38
PGS. SENT 1
RESULT OK



KCIA AIRPORT ADVISORY

DATE: April 9, 2003

TO: King County International Airport Tenants
distributed by e-mail and fax

FROM: Jamie Runyan, Airport Operations & Compliance Officer

SUBJECT: Surface Measurement Activity Tonight on Main Runway 13R/31L

As you are aware, our regular monitoring inspection program for main runway 13R/31L had identified a potential area of settlement between Bravo-3 and Bravo-4. Last month, survey and testing activities were performed in this area and, as a result, further examination of an additional 4,000 feet of runway is now required.

Tonight a crew will be using portable equipment to measure elevation changes along the main runway. This surface testing activity is scheduled to begin at 21:00 hours Wednesday, April 9th and finishing at approximately 09:00 hours on Thursday morning, April 10, 2003.

The testing will not require closure of runway 13R/31L as the measuring activities can be temporarily suspended. A NOTAM will be issue for Personnel and Equipment Working (PAEW) on 13R/31L with ten minutes Prior Permission Required (PPR). The short runway 13L/31R will remain open. Please check NOTAMS for current information.

We apologize for any inconvenience caused by this short notice. Your continued patience and cooperation in allowing the Airport to further evaluate the runway surface and design repairs is greatly appreciated. Should you have any questions, please contact me directly at (206) 296-7332.

KCSlip4 34470

SEA401017

*** TX REPORT ***

TRANSMISSION OK

TX/RX NO 2955
CONNECTION TEL 55055
SUBADDRESS
CONNECTION ID KING CTY AIRPORT
ST. TIME 04/09 15:53
USAGE T 01'17
PGS. SENT 1
RESULT OK



KCIA AIRPORT ADVISORY

DATE: April 9, 2003

TO: King County International Airport Tenants
distributed by e-mail and fax

FROM: Jamie Runyan, Airport Operations & Compliance Officer

SUBJECT: Surface Measurement Activity Tonight on Main Runway 13R/31L

As you are aware, our regular monitoring inspection program for main runway 13R/31L had identified a potential area of settlement between Bravo-3 and Bravo-4. Last month, survey and testing activities were performed in this area and, as a result, further examination of an additional 4,000 feet of runway is now required.

Tonight a crew will be using portable equipment to measure elevation changes along the main runway. This surface testing activity is **scheduled to begin at 21:00 hours Wednesday, April 9th and finishing at approximately 09:00 hours on Thursday morning, April 10, 2003.**

The **testing will not require closure of runway 13R/31L** as the measuring activities can be temporarily suspended. A NOTAM will be issued for Personnel and Equipment Working (PAEW) on 13R/31L with ten minutes Prior Permission Required (PPR). The short runway 13L/31R will remain open. **Please check NOTAMS for current information.**

We apologize for any inconvenience caused by this short notice. Your continued patience and cooperation in allowing the Airport to further evaluate the runway surface and design repairs is greatly appreciated. Should you have any questions, please contact me directly at (206) 296-7332.

KCSlip4 34471

SEA401018

*** MULTI TX/RX REPORT ***

TX/RX NO	2949	
PGS.	1	
TX/RX INCOMPLETE	[*017]9p7675440	BFI AVIATION
	[*021]9p7632590	FEDEX
	[*024]9p4333619	GENISIS AIRCRAFT
	[*033]9p7626046	LINDEAN AIRCRAFT
	[*038]9p7672549	NW EXEC AIR
	[*040]9p7638421	RAYTHEON AIRCRAF
	[*046]9p7860483	TC AVIATION
	[*067]9p6220837	ROLING FLIGHT
	[*070]9p6550667P	DEPT OF DEFENSE
TRANSACTION OK	[*003]9p7621223	AIR TRANSPORT
	[*004]9p7630381	AIRBORNE EXPRESS
	[*006]9p7626357	AIRPAC AIRLINES
	[*007]9p7632036	AMERICAN AVIONIC
	[*008]9p7636239	AMERIFLIGHT
	[*009]9p7621158	AVIATION PARTNER
	[*010]9p7633428	AVIATION BOOK CO
	[*011]9p7647112	AVIATION TRAINIG
	[*012]9p7633428	AVIATOR STORE
	[*015]9p7620611	BAX GLOBAL
	[*016]9p6555116	BOEING CO
	[*018]9p7648124	CALIBER INSPECT
	[*019]9p7674018	CLASSIC HELICOPT
	[*022]9p7680888	FLIGHTCENTER
	[*023]9p7679333	GALVIN FLYING
	[*025]9p7689700	GUIDO PERLA & AS
	[*026]9p7689458	HELIJET
	[*027]9p7679333	KING BROADCASTIN
	[*028]9p7641904	KC JETCENTER
	[*029]63838	EMERGENCY MGMNT
	[*030]60514	SAFETY & CLAIMS
	[*031]64271	GUARDIAN ONE
	[*032]64271	SPECIAL OPS
	[*035]9p7641312	NATIONAL AVIATIO
	[*036]9p7681715	NORDSTROM
	[*037]8p120329p6042782608	N VANCOUVER AIR
	[*039]9p7634837	PISTOL CREEK FIN
	[*043]9p7623542	SEATTLE JET STRM
	[*044]9p7633320	SERVICE GROUP
	[*045]9p7630381	SOUND AERIAL SVY
	[*047]9p7641986	TAG AVIATION
	[*048]9p7674920	UPS
	[*049]9p5536851	US CUSTOMS
	[*050]9p5530190	US IMMIGRATION
	[*051]9p7643862	VALKERIE CORP
	[*052]9p7644760	WA AUDIOLOGY
	[*055]9p7681947	WEST ISLE AIR
	[*056]9p7674539	WESTERN METALS
	[*057]9p7679464	WINGSALOFT
	[*058]9p7645707	MUS OF FLIGHT
	[*059]8p120329p6042735301	HELIJET
	[*060]8p120329p3602930517	WEST ISLE AIR
	[*061]9p7630381	AIR TRANSPORT
	[*062]9p7635156	S SEATTLE CC
	[*064]9p7622997	DUNCAN AVIONICS

ERROR INFORMATION	[5]9p7677662	GALVIN-MAIT BLDG
	[*06]9p7633964	MENTE AVAITION
	[*069]8p947395p6142381807	AIRNET
	[*071]8p947395p5098840534	EXECUTIVE FLIGHT
	[*072]9p7637761	OTTER CORP
	[*073]9p2533952458	AIRBORNE EXPRESS
	[*074]9p6551454	BOEING
	[*005]9p7318558	AIRLIFT NW
	[*013]9p7670755	AVOLO
	[*014]9p2535291081	B&B AIRCRAFT
	[*053]9p7671600	WA AIR NATL GRD
	[*054]9p7644001	WA AERO
	[*063]9p7637124	AMERICAN FLYERS
	[*068]9p4252265314	FBL JET
[*075]9p6762645	NATIONAL CHARTER	



KCIA AIRPORT ADVISORY

DATE: April 9, 2003

TO: King County International Airport Tenants
distributed by e-mail and fax

FROM: Jamie Runyan, Airport Operations & Compliance Officer

SUBJECT: Surface Measurement Activity Tonight on Main Runway 13R/31L

As you are aware, our regular monitoring inspection program for main runway 13R/31L had identified a potential area of settlement between Bravo-3 and Bravo-4. Last month, survey and testing activities were performed in this area and, as a result, further examination of an additional 4,000 feet of runway is now required.

Tonight a crew will be using portable equipment to measure elevation changes along the main runway. This surface testing activity is **scheduled to begin at 21:00 hours Wednesday, April 9th and finishing at approximately 09:00 hours on Thursday morning, April 10, 2003.**

The **testing will not require closure of runway 13R/31L** as the measuring activities can be temporarily suspended. A NOTAM will be issue for Personnel and Equipment Working (PAEW) on 13R/31L with ten minutes Prior Permission Required (PPR). The short runway 13L/31R will remain open. **Please check NOTAMS for current information.**

We apologize for any inconvenience caused by this short notice. Your continued patience and cooperation in allowing the Airport to further evaluate the runway surface and design repairs is greatly appreciated. Should you have any questions, please contact me directly at (206) 296-7332.